Panasonic

WV-SP508/SP509/SW558/SW559 Firmware Release Note

This document describes WV-SP508/SW558Series firmware version up (Application Firmware) Information.

1. Release version: Version 1.10

2. Release Note Reference Number: SP509_003

VER (ActiveX VER) Release Date	Priority Rank Level				k	Priority Rank Level A:Recommend to apply (Major or serious update) B:When issue happened C:Maintenance timing U :Function /Performance improvement (Not Necessary to updat		te)													
		Α	в	С	U	Issue (Phenomenon)		Occurrence condition	0												
1.06 (4.08.00) Mar.,'12	С				х	-		-	Improved Start up Time at low tempera												
	с					Failed to capture a camera picture by Snap shot button on web browser. (Occurrence frequency: Low)	like 3-N JPEG	ting to capture a snap shot at high resolution JPE0 lega in HTTPS. Most of cases are at 3 Mega picture high resolution that takes more than 10 s for data processing.	Fixed to display a snap shot properly. Still it may occur if it would take more t volume. To avoid it, please make settings chan be [QVGA] or [JPEG]-[Quality] to be lo												
1.07						Alert may be displayed on SF548 and SF538 (those models do not have SD card slot). (Occurrence frequency: Low)		-	Fixed not to display the alert.												
(4.08.00) Apr.,'12						Video streaming may be stopped. (Occurrence frequency: Low)	NWDR	se power source were PoE and connecting with (keeping power "on"), then power of PoE to be ce and retain to "on".	Fixed not to stop streaming.												
						JPEG recording may be stored 1st JPEG picture only and failed to do afterwards. (Occurrence frequency: Mid)	In a ca changi	se recording in H.264 onto SD memory card and ng configuration from H.264 to JPEG.	Fixed to record properly.												
						_		-	Improved picture quality at Super Dyna												
						-		-	Improved picture quality more at Supe												
1.08 (4.08.00)	C					Video streaming may be stopped when receiving a command. (Occurrence frequency: Low)	switche	se start streaming/stop streaming in RTSP were ed, repeatedly. does not occur using with Panasonic recorders.	Fixed not to stop streaming.												
(4.08.00) May,'12		C	C	C .	C		C	C	C	0	C		U U					Restart the unit, unexpectedly. (Occurrence frequency: High)	overla 1. IPv(RA. 2. And	bens when the following two conditions o; 5 router gives IPv6 address with a prefix for ther IPv6 address that is 38-character or including prefix, exists in same network.	Fixed not to restart.
				_	х	_		-	The Ex Optical Zooming will be initializ do it by software on previous version.												
1.09 (4.08.00)	с			x		WV-SP509 and WV-SP508 only: Auto-focus function may not bring optimum focusing. (Occurrence frequency: High)	It seem	s to realize at "Wide" position	Improved auto-focus function bringing												
June,'12		[]			Х	-		-	Improved picture quality (looks higher-												
				Х		Camera picture may not be displayed. (Occurrence frequency: High)		se connecting with NV200 and 16 multi-picture on to be selected.	Fixed to display camera picture proper												

Correspondence
rature environment.
than 30 seconds for data processing depends on data
nged either [JPEG]-[Resolution] of [JPEG/H.264]-tab to ower.
namic "ON".
er Dynamic "ON".
ized (Default reset) by [INITIAL SET] button, addition to
g optimum focus.
r-definition).
erly.

Panasonic

WV-SP508/509/SW558/SW559 Firmware Release Note

This document describes WV-SP508/SW558Series firmware version up (Application Firmware) Information.

1. Release version: Version 1.10

2. Release Note Reference Number: SP509_003

VER (ActiveX VER) Release Date	Pr	Priority Rank Level			Priority Rank Level A: Recommend to apply (Major or serious update) B:When issue happened C: Maintenance timing U :Function /Performance improvement (Not Necessary to upda	te)	Contents			
		Α	вс	; U	Issue (Phenomenon)	Occurrence condition	Correspondence			
				x	-	-	Reduced bandwidth (approx. 5% reduced than version 1.21) on H.264 while Super Dynamic is ON.			
1.10 (4.08.00) July,'12			>		Between NV200 and camera, disconnect every some minutes and no video (solid black) after freezing, repeatedly. (Occurrence frequency: High)	In a case, connecting with NV200 and the camera were registered on NV200 by OnVIF.	Fixed not to disconnect.			
	с		>	ζ.		While connecting with WV-NV200 and WV-NV200 has assigned IP address.	Fixed EasyIPConfig software to display properly.			
			>		Restart, unexpectedly. (Occurrence frequency: Mid)	In a case receiving many requests for starting H.264 stream like switching cameras sequentially on ASM200 or requested by two or more clients.	Fixed not to restart.			