

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)					*: ONVIF is a trademark of Onvif, Inc.		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver1.44 (4.50.14) June,'17	-				First production.			
Ver1.45 (4.50.14) June,'17	C			x	Not working VMD function after a power cycle (turned power off then on) even if the VMD setting were activated.	On firmware version 1.44.	Fixed.	
Ver1.46 (4.50.14) June,'17	U			x	Due to factory reason. This is to improve the face recognition function which is recommended only for the other WV-Sxxxx cameras only.			
Ver1.47 (4.50.14) Sept.,'17	C			x	Aborted video transmission in multicast transmission.	When "On" is selected for "Stabilizer".	Fixed.	
Ver1.48 (4.50.14) Oct.,'17	C			x	Camera picture may be solid black.	-	Fixed.	
Ver1.70 (4.50.20) Nov.,'17	C			x	-	-	Added a support page and so that it possible to access to support page by QR code.	
				x	-	-	RTSP distribution abolished the constraint which was only unicast while selecting multicast.	
				x	-	-	In CGI command, expanded the parameter of "get_io2". Added response format "3" so that information on sound detection / command alarm / i-VMD could be acquired.	
				x	-	-	Profile S compliant service on ONVIF®, made available for streaming in H.265 settings.	
				x	-	-	Added a message in the setting screen for SD memory card; "It is not available when "60fps" is selected for [Image capture mode]."	
				x	-	-	Changed the hue etc. even if only the brightness were changed.	
			x		Missing display the "VMD / i-VMD" column in i-VMD "Alarm".	In Spanish only.	Fixed.	
			x		When setting i-VMD depth, after drawing and registered rectangle, the coordinates of the rectangle would be shifted in the upper left direction when the screen was redisplayed.		Fixed.	
			x		At displaying system log, display the log in two lines. Also display shifting the date and time of occurrence and contents column each other.	In case outputting log with a long character string.	Fixed.	
			x		Camera may reboot by changing image capture mode.	When use with recorder.	Fixed.	

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)			Contents		
							*: ONVIF is a trademark of Onvif, Inc.				
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence				
Ver1.70 (4.50.20) Nov.,'17	C			x	Camera may reboot by accessing with a browser other than Internet Explorer (IE).	-	Fixed.				
				x	VMD area may not be able to set at second time and after.	-	Fixed.				
					x	-	-	Deleted encryption protocol TLS 1.0 for security purpose.			
				x	RTSP connection may be disconnected upon receiving an incorrect RTSP request.	-	Fixed.				
				x	RSTP connection may be disconnected very rarely by sending RTSP request reception and RTSP response transmission at the same time.	-	Fixed.				
				x	-	-	Improved communication quality on video streaming in H.265/H.264.				
Ver1.80 (4.50.20) Dec.,'17	C				x	-	-	Added SD memory card password lock function.			
				x		-	-	Fixed an issue in the cgi command "/Set?Func=Bright&Kind=1&Data=-2"			
Ver1.82 (4.50.20) Mar.,'18	C					-	-	Changed factory default setting values as follow; 传送模式: 恒定速率 带宽(每个客户端: 3072kbps 音频模式: 音频输出 输入音量: 线路 中 AGC(音频): Middle			
					x	The specified image capture size may not be obtained even if it were specified with ImageViewer by CGI command.	-	Fixed.			
					x	-	-	Improved auto focus convergence speed quicker.			
				x		Administrator password may be deleted.	-	Fixed.			
1.90 (4.50.20) June, '18	C				x	-	-	Changed factory default setting for Authentication method; Previous: "Digest or Basic" New: "Digest"			
								For more details: security_upgrade_June2018.pdf			
					x	-	-	Changed password policy that it must include at least 3 types of characters among "upper case letters / lower case letters / numbers / symbols". For more details, click here. Note: Original passwords and authentication method of products on the system are kept unchanged even firmware and software have been updated.			
								For more details: security_upgrade_June2018.pdf			
					x	-	-	Added user authentication at host authentication.			

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)							
						*: ONVIF is a trademark of Onvif, Inc.		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
1.90 (4.50.20) June, '18				x	-	-	Changed saving setting data with encryption. Note: unable to restore the setting data if you would downgrade the firmware.	
				x	-	-	Made some other security measures enhanced.	
				x	-	-	Added "Drawing method", "Decoding options" and "Frame Skip Options (When PC is Heavy Processing Load)" onto plug-in software.	
				x	-	-	Added "Reboot" to "Schedule".	
				x	-	-	Added "<< Latest 100", "Number of pages display" in "Systemlog".	
				x	-	-	Added a choice of "2pics/2s" for "Transmission interval" setting of "Transmission mode" in "Best shot function". Note: Concerning the models on this document, no models are recommended to use the Best shot function.	
				x	-	-	Changed factory default setting for "Bandwidth control(bit rate)" Previous: Unlimited New: 51200kbps	
			x		Communication may be disconnected when acquiring network information with SNMP.	-	Fixed.	
			x		Network connection may not be possible due to the MAC address authentication with the network device may not be done properly at startup.	-	Fixed.	
		x			Temperature compensation at lens may not work correctly and the focus sometimes shifts little by little.	-	Fixed.	
			x		Unable to configure the setting relating to the e-mail notification by the cgi command "reg_mailaddr".	-	Fixed.	
			x		Focusing may not work.	-	Fixed.	
Added on July 27,2018			x		If an RTSP header contains two or more User-Agent headers. no HTTP400(Bad Request) error returned and ignore the second and subsequent User-Agentheaders.	-	Fixed.	
			x		It was usable even if the certificate for using HTTPS has expired.	-	Fixed.	
1.91 (4.50.20) July, '18	C			x	Solid black screen may appear during sequencing with the network disk recorder due to it takes time to output the video.	-	Fixed.	

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
1.91 (4.50.20) July, '18	C			x	SD memory backup recording did not stop.	By turning power on / off while SD memory backup recording during connecting with the network disk recorder.	Fixed.	
				x	Revised on Sept. 7, 2018 Camera may reboot, unexpectedly.	When sequencing the network disk recorder and or the video management software (WV-ASM series) with "SD memory backup" enabled simultaneously.	Fixed.	
				x		By downloading the SD memory backed up data with the network disk recorder	Fixed.	
				x	Recording may not retain when restarting camera.	In an environment where the communication state is unstable	Fixed.	
				x	Recording may not stop at restoration of communication		Fixed.	
Revised on Aug. 9, 2018				x	Did not work Hardware decode of plug-in software may not work when selecting compression method "H.265".	-	Fixed.	
1.92 (4.50.34) Aug., '18	C		x		Frame rate and bit rate may drop.	By transmitting H.264/H.265/JPEG live images continuously over 1 year without being rebooted.	Fixed.	
				x	Camera may restart by disconnecting the camera's LAN cable while transmitting video in UDP.	In AC power operation.	Fixed.	
1.93 (4.50.34) Oct., '18	C			x	When Image quality to be set in Motion priority (Frame rate), picture may not be displayed according to the frame rate. (Occurrence frequency : Rare)	-	Fixed.	
				x	ONVIF RTSP Multicast may not be transmitted.	-	Fixed.	
1.94 (4.50.34) Nov., '18	C			x	Multicast related settings ("Transmission type" setting and some others) may restore to the factory default settings by upgrading firmware from version 1.82 (or earlier) to version 1.90 (or later).	-	Fixed.	
Ver2.00 (4.50.34) Dec., '18	C			x	-	-	Improved detection capability of "face wearing a mask" at detecting face by Facial Recognition Server Software, WV-ASF950, etc. Note: Not recommended product for Face best shot function.	
				x	-	-	Settings of "HTTP max segment size(MSS)" to be relating to the camera action; - JPEG transmission for Face Best Shot - "HTTP alarm notification"	

*: ONVIF is a trademark of Onvif, Inc.

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					<div>Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)</div>			Contents		
	*: ONVIF is a trademark of Onvif, Inc.										
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence				
Ver2.00 (4.50.34) Dec.,'18	C			x		Camera may restart, unexpectedly. (Occurrence frequency: Rare)	In case of high load such as multi-stream transmission at 60fps etc.	Fixed.			
				x			By receiving ONVIF command continuously.	Fixed.			
				x		Camera may send corrupt AAC-LC data.	When the transmission is delayed due to the network environment etc.	Fixed.			
				x		Video distribution may not be possible.	When the configuration of UI setting for Baseline Profile were as follow; - 30fps, H.264, FHD, Other than VBR	Fixed.			
				x		Communication error may occur. (Occurrence frequency: Rare)	While connecting with Network Disk Recorder, WJ-NX series.	Fixed.			
Ver4.00 (4.50.35) Feb.,'19	C				x	-	-	Added “Overlay Image” function.			
					x	-	-	Added "VIQS (Variable Image Quality on Specified area)” function.			
					x	-	-	Added a choice of "On(Frame rate control)" to "GOP Control" in "Smart coding".			
				x		The refresh interval value may not be reflected in the CGI command as follow; /cgi-bin/set_h264?f_priority=4&nr_framerate=1&h264_bandwidth=64&h264_quality=9&h264_ivop=0.2	-	Fixed.			
				x		Black screen may be displayed back while recording H.264/H.265 to SD memory card and turning power Off and On.	-	Fixed.			
					x	-	-	Improved resolution feeling in JPEG still image update at multiscreen in full screen display.			
				x		May not be able to change the save destination at the time of FTP periodical transmission error.	-	Fixed.			
				x		The settings of SMTP server may return before the setting by restarting the camera.	-	Fixed.			
					x	-	-	Changed the URLs of hype-link destination according to change of support page URL (from "http" to "https").			
				x		Displayed full screen on the main monitor when placing IE on the sub monitor and clicking the full screen display button.	When using the two monitor screens of main and sub.	Fixed.			
					x	-	-	Improved the visibility of characters in the date/time screen.			

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level					Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.00 (4.50.35) Feb., '19					-	-	Changed factory default settings as follow; - Internet mode (over HTTP) from "On" to "Off" - Image capture mode from 30fps to 25fps, SD from "Off" to "On" - Date/time display format from "DD/MM/YYYY" to "YYYY/MM/DD" - Time zone from "GMT+00:00" to "GMT+08:00"	
				x	-	-	Added a message as follow in the "Schedule" page; "VMD permission" is required when assigning the period to be detected. Setting is not necessary when detection at any time.	
					-	-	Changed a message by clicking the Delete button in the log list window to; Delete the log and image as the result of retrieval including the page where log is not displayed. (All of data selected by "Event" and "Recording time" are deleted.)	
					The recorded data of the log one before the relevant time might be downloaded when downloading the recorded data from the log list.	-	Fixed.	
			x		The area setting of the privacy zone may shift little by little each time clicking the setting button.	-	Fixed.	
				x	-	-	ONVIF ProfileT Supported Scope/Scene Change Event, Property/DeviceIO/Metadata Sync.	
				x	-	-	ONVIF ProfileT Supported Scene Change Event.	
				x	-	-	ONVIF ProfileT Supported ONVIF Event Content Filter.	
			x		There was an issue at GetVideoEncoderConfigurationOptions in ONVIF 60fps mode.	-	Fixed.	
			x		Camera may restart unexpectedly while receiving ONVIF command continuously.	-	Fixed.	
			x		XML may be a syntax error by ONVIF Event command due to the XML namespace prefix was not defined at WS-Addressing.	-	Fixed.	
			x		Multicast parameters did not appear in the Milestone stream setting when ONVIF camera was registered in Media 2.	-	Fixed.	
				x	-	-	Changed the response of "/cgi-bin/get_io2?format=3&"; It became not to notify CGI response each time even if detecting command alarm continuously.	

*: ONVIF is a trademark of Onvif, Inc.

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)			Contents		
							*: ONVIF is a trademark of Onvif, Inc.				
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence				
Ver4.00 (4.50.35) Feb., '19	C			x	When one network is disconnected from the network, the same alert screen is displayed for other cameras.	While using multi-screen display.	Fixed.				
				x	Camera may restart when a file which cannot be deleted were created during JPEG overwrite recording on the SD memory card.	-	Fixed.				
					x	-	-	Made Stream(3) available when “On” is set for Stabilizer.			
				x	RTC communication may not be normal in rare cases when turning power from OFF to ON.	-	Fixed.				
				x	When deleting SD card data on the log list screen, data that can not be deleted may be left while displaying the play window.	-	Fixed.				
				x	Camera may restart upon receipt of certain CGI commands (those are to change H.264/H.265 1st stream quality / bitrate / resolution without disconnect the stream).	While face detection or face best-shot is enabled.	Fixed.				
				x	Transmission type (H.264/H.265) and image capture size of stream may not be changed (transmission type and image capture size hold before change).	If those were changed within 2 minutes after the network had been disconnected with over RTSP connection.	Fixed.				
					x	-	-	Improved visibility of "SDREC" button on the window for tablet PC.			
Ver4.01 (4.50.35) Feb., '19	B			x	The oldest recorded data may bot be able to play back.	When the setting of overwrite recording to SD memory card is "On".	Fixed.				
				x	Communication may stop even if connected with a PC or switch after starting up by PoE injector or external power supply (24V AC / 12V DC).	-	Fixed.				
Ver4.02 (4.50.35) Apr., '19	B		x		After upgrading the firmware from version 2.00 (or earlier) to 4.00 or 4.01, flicker caused by fluorescent light may not be prevented even if setting either "Indoor scene / 室内场景 (50Hz)" or "Indoor scene / 室内场景 (60Hz)" at "Light control mode / 光量控制模式".	-	Fixed.				

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level							
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.10 (4.50.35) June,'19				X	-	-	Security has been enhanced.	
			X		Audio may not output by attempting to connect two sessions simultaneously and failure to authenticate one of them.	-	Fixed.	
				X	-	-	Added a note in the window of DDNS setting page when using "Dynamic DNS Update", "Dynamic DNS Update(DHCP)".	
				X	-	-	Supported multi-browsers other than the Internet Explorer. Some restrictions apply: click here for details.	
				X	-	-	Improved smooth text display by changing the texts on the screen from 2 gradations to grayscale.	
				X	-	-	Added a CGI command to make an alarm; /Set?Func=SoftTrigger or /cgi-bin/Set?Func=SoftTrigger or /cgi-bin/comalarm.cgi	
					-	-	Changed factory default setting of the time zone to Chinese Standard Time(CST), UTC+8.	
				X	-	-	Added parameters of get_capability, CGI command, for motorized variable focal lens; - Enable/disable and Magnification of EX-Zoom.	
				X	-	-	Added interference detection information to additional information when using the i-VMF function of Extension software.	
				X	-	-	Display the license of open source software (OSS) on upgrade screen.	
			X		ONVIF communication may become a cause of destroying resources.		Fixed.	
			X		-	-	Fixed Session Description Protocol/SDP (IPv6) on ONVIF.	
			X		Unable to find ONVIF search.	-	Fixed.	
			X		JPEG frame rate setting display becomes 0.33 fps by changing image capture mode from 25 fps to 30 fps with CGI (/cgi-bin/setdata?IMG_MODE) although actual transmission rate is 5 fps.	-	Fixed.	
				X	-	-	Supported On-Screen Display (OSD) in Chinese.	
				X	-	-	The file may not be found by opening the log list during overwrite recording of the SD memory card and attempt to browse.	
				X	-	-	Improved responses to ONVIF commands for PTZ cameras.	

*: ONVIF is a trademark of Onvif, Inc.

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level					Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.10 (4.50.35) June,'19	C			x	PTZ may not stop even if it received stop command in ONVIF.	-	Fixed.	
				x	-	-	The camera may restart by encrypting the stream 1 only, selecting audio transmission mode AAC-LC and recording video and audio simultaneously.	
				x	-	-	Improved accuracy of Click-to-Center".	
				x	Displayed "Approx. 2 min." for an alert of initializing operation.	-	Corrected the display to "3 min".	
				x	Displayed "8 min" at upgrading firmware with selecting "Reset the settings to the default after completing the upgrade".	-	Corrected the display to "11 min".	
Ver4.11 (4.50.35) July,'19	C			x	The face best-shot image used to display face search history data on Video Management Software may not be created correctly. (Occurrence frequency: Rare)	-	Fixed. Note: The cameras are NOT recommended to use the face best-shot function.	
				x	The camera may restart when live sequence display by network disk recorder or Video Management Software without distributing H.264 or H.265 for recording. (Occurrence frequency: Rare)	-	Fixed.	
Ver4.20 (4.50.35) Sept.,'19	C			x	-	-	In FTP / SNMP authentication, "Authentication error" is logged in the system log by failing authentication more than a certain condition.	
				x	-	-	Supported EasyIpSetup software (Ver4.31R00) and became to display serial numbers of devices.	
				x	-	-	Updated (Enhanced) SNMP MIB information. The document of i-PRO camera management information (MIB) is available at the following URL; https://security.panasonic.com/training_support/panasonic_device_integration/snmp-mib/	
				x	-	-	Improved so that available to connect with HikVision recorder by CGI command.	
				x	Recording may not stop when changing imaging capture mode.	-	Fixed.	
				x	VMD Alarm may not detect crossing the line at the bottom of the screen.	-	Fixed.	
				x	The slide-bar for VMD may not be able to be slid.	In Compatibility View mode on Internet Explorer.	Fixed.	

*: ONVIF is a trademark of Onvif, Inc.

Corrected on Nov.
6, 2019

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					<div>Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)</div>			Contents <div>*: ONVIF is a trademark of Onvif, Inc.</div>		
		A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence			
Ver4.20 (4.50.35) Sept.,'19	C			x		The camera may restart due to memory access error. (Occurrence frequency: Rare)	-	Fixed.			
Ver4.22 (4.50.35) Nov.,'19	C			x		"Transmission type" and "Multicast address" configured by system configuration tool, may not be saved.	-	Fixed.			
					x	-	-	Improved a phenomenon that CPU load might increase after updating for V4.20.			
Ver4.23 (4.50.38) Jan.,'20	C				x	-	-	Supports multi-browsers Google Chrome, Firefox and Microsoft Edge in addition to Internet Explorer for; - the setup screen of the extension function "i-VMD" - i-VMD frame display on the live image - the face detection frame on the live image			
					x	-	-	Changed the company name in the plug-in software Active X to the new one.			
				x		Rebooting may cause the image to be out of focus when the extension function "face best-shot" is enabled.	-	Fixed.			
Ver4.25 (4.50.38) Mar.,'20	C			x		The camera may restart unexpectedly due to the irregularity in the data transmission/receiving process in the memory. (Occurrence frequency: Rare)	-	Fixed.			
				x		The camera may restart unexpectedly due to the irregularity in the alive monitoring process. (Occurrence frequency: Rare)	-	Fixed.			
				x		The camera may show black images on its "Live" window. (Occurrence frequency: Rare)	-	Fixed.			

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)					*: ONVIF is a trademark of Onvif, Inc.		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.30 (4.50.38) April,'20	B				x	-	-	Added “SNMP trap setting” in [Network] > [Advanced] > [SNMP]. (Please refer to "New functions and addendum" for detail.)
					x	-	-	Added a CGI command "/cgi-bin/setup_menu_disp?25fps=1" to make 25/50fps selectable on the "Image capture mode" menu.
			x			All sessions get disconnected by executing the ONVIF® commands for changing the framerate and the resolution.	-	Fixed.
				x		-	-	Changed the date character string format for response which responds via SNMP to "DateAndTime" format as it was not transmitted correctly.
					x	-	-	Supports multi-browsers Google Chrome, Firefox and Microsoft Edge in addition to Internet Explorer for; - Playing back the images on SD memory card (Click here for detail)
					x	-	-	Changed the URL, QR code and Data_Matrix linked to the support page on the "Support" menu.
				x		On the "/cam" window for mobile terminal, reloading the image will show the normal live images when the camera is switched to the "Access permission" period from inaccessible period.	-	Fixed.
					x	WV-S1432LH Only		
					x	-	-	Improved the response when reconnecting in HTTPS connection on Windows 10.
			x			Selecting the image capture size on the "Image" tab may change the bit rate to 3Mbps.	-	Fixed.
				x		-	-	Corrected the coordinate of the transmitted contents in ONVIF Metadata.
			x	-	-	Enhanced the access restriction function of SNMP v1/v2. (Please refer to "New functions and addendum" for detail.)		

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level					Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.30 (4.50.38) April,'20	B						Improved the image quality as followings: 1. Motion-blur in low light level Reduced the image lag under the low light condition to improve the visibility of moving objects. 2. Resolution Improved to be more natural resolution and outlines 3. Blocked up shadows in dark areas Improved to illuminate the dark areas (Click here for detail)	
							Enhanced security.	
							Changed the below default setting. - [Internet mode]: from "OFF" to "ON" - [Viewer software (nwc4Ssetup.exe)] - [Smoother live video display on the browser (buffering)] from "ON" to "OFF". (Please refer to "New functions and addendum" for detail.)	
							Fixed.	
							Fixed.	
							Changed the company name in the plug-in software Active X to the new one.	
Ver4.31 (4.50.38) July,'20	B	x			The camera keeps changing the image brightness to low and high alternately until it is rebooted. (Occurrence frequency: High)	When the camera operates continuously with [Image capture mode] set to the default value "30fps mode" for more than approx. 2 years* without being rebooted. * This period will be shortened to approx 1 year for "60fps mode".	Fixed.	

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level							
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.50 (4.50.38) Nov., '20	B		x		The camera may reboot. (Occurrence frequency: Low)	Continued operation of the following: - sequence display with a network disk recorder - sequence display with WV-ASM series software when [Live image source] is set to "Camera"	Fixed.	
				x	-	-	Changed the behavior related to bit rate when the communication protocol is changed from "HTTP" to "HTTPS" as below. Previous versions: the camera automatically sets the bit rate to 4 Mbps when the selected one is larger than 4 Mbps. This version or later: the camera does not change the bit rate.	
Ver4.60 (4.50.38) Feb., '21	C			x	-	-	Improved the response to the CGI command "/cgi-bin/get_io2" by adding VMD ratio in percentage.	
				x	-	-	Changed the default setting of [Transmission priority] to "VBR" when the browser's language is not Japanese.	
				x	-	-	Changed the default setting of [Network Settings] in [Setup]-> [Network] page-> [Network] tab, from "Auto(Advanced)" to "DHCP".	
				x	-	Revised: March, 2021	Added the On/Off setting for the Secure Real-time Transport Protocol (SRTP) function to the [Advanced] tab in [Setup]-> [Network] page.	
				x	-	Revised: March, 2021	Improved the [HTTP alarm notification] function as follows: 1. Supports Digest authentication - The camera performs either "Digest" or "Basic" authentication according to the response from the HTTP server when initially accessed without ID and password. 2. Adds an error log for the failure in HTTP server user authentication - Displays "<HTTP alarm notification> authentication error" in the system log when the authentication fails. 3. Supports HTTPS Communication - Entering "https://" in [Address] enables HTTPS communication.	
				x	-	-	Added the On/Off setting for ONVIF® to the [Network] tab in [Setup]-> [Network] page. (Default : On)	
				x	-	-	Added the following note to the "HTTPS" window in [Setup]-> [Network] page-> [Advanced] tab. - When "HTTPS" is selected for "Connection", the maximum bandwidth(bit rate) is limited to 16Mbps.	

*: ONVIF is a trademark of Onvif, Inc.

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level							
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
Ver4.60 (4.50.38) Feb., '21	C			x		-	-	Corrected the RTSP protocol for transmitting H.265 images using ONVIF®.
				x		The camera does not issue a terminal alarm. (Occurrence frequency: High)	After the camera issues a terminal alarm, and the user turns off the terminal alarm during the time set in [Alarm deactivation time].	Fixed.
				x		The camera may reboot. (Occurrence frequency: Rare)	While performing JPEG recording.	Fixed.
				x		The camera does not display the full-width left parenthesis "(" on the live image.	-	Fixed.
				x		UDP communication may be disconnected depending on the network environment. (Occurrence frequency: Rare)	When transmitting high resolution or high bit rate images.	Fixed.
				x		-	-	Enhanced security.
Ver4.70 (4.50.38) Mar. '21	B			x		-	-	Enhanced security.
				x		The camera may reboot when connected to WV-ASM300. (Occurrence frequency: High)	When the camera repeatedly receives the requests to start and stop transmission from WV-ASM300 at short interval.	Fixed.
Ver4.80 (4.50.38) July, '21	C			x				Added the following actions for SD memory card error: - Displays the following alert when a bit rate higher than "6144kbps" is selected in [Max bit rate (per client)*]: "Since the value of "Max bit rate (per client)" of H.265/H.264 recording stream set for "Recording format" is larger than "6144kbps", there is a possibility an abnormality will occur in continuity of recorded video. It is recommended to set it to "6144kbps" or less." - Records SD memory card logs on the [Status] tab in the [Maintenance] page, in the case of loss of recording or abnormal response from an SD memory card - Sends Panasonic alarm protocol "Diag." to the destination servers designated in the [Notification] tab of the [Alarm] page, in the case of abnormal response from an SD memory card
				x		-	-	Added the "Download" function to "Viewer software (nwc4Ssetup.exe)" in the [Basic] tab of the "Basic" page.
				x		-	-	Increased the maximum password length from 32 to 128 characters for "Authentication" in the [Network] page-> [Advanced] tab-> "SMTP(E-mail)".
				x		-	-	Corrected the camera response to the CGI command "cgi-bin/setdata".

*: ONVIF is a trademark of Onvif, Inc.

Corrected: April, 2021

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.80 (4.50.38) July, '21	C			x	The camera may show a black image. (Occurrence frequency: Rare)	When the setting in [Image capture size] or [Image capture mode] is changed repeatedly.	Fixed.	
				x	-	-	Corrected the camera response to the "GetVideoEncoderConfigurationOptions" command of ONVIF Profile S.	
				x	Unable to upgrade firmware. (Occurrence frequency: Rare)	When failing to upgrade firmware due to a power failure	Fixed.	
Ver4.81 (4.50.50) Sept., '21	U				-	-	Changed the digital signature of the viewer software (nwc4Ssetup.exe) from "Panasonic Corporation" to "Panasonic i-PRO Sensing Solutions Co., Ltd."	
Ver4.90 (4.50.50) Nov., '21	U				x	-	Added Link Layer Discovery Protocol (LLDP) setting tab to the [Advanced] tab on the [Network] page.	
					x	-	Added a CGI command to transmit H.265/H.264 stream without NAL unit. Without NAL: "cgi-bin/setdata?H264NONALFLG=1" With NAL (default): "cgi-bin/setdata?H264NONALFLG=0"	
Ver4.91 (4.50.38) Dec., '21	B				x		Added the following note under the on/off setting of "Internet mode" on the [Image] tab in the [Image/Audio] page: "When "On" is selected, streams will be transmitted using the HTTP port. When "Off" is selected, streams will be transmitted using the UDP port."	
					x		Added the "Set PC time to the camera" checkbox to the "Date/time" field on the [Basic] tab.	
					x	-	Added supported browser information to the camera response to IP Setting Software and the CGI command "getinfo".	
					x	-	Changed the alarm name from "Panasonic alarm protocol notification" to "TCP alarm notification".	
					x	-	Added Subject Alternative Name (SAN) to the certificate signing request (CSR) for creating an HTTPS server certificate.	
					x	-	Added "NTP test" function to the "NTP" window on the [Advanced] tab in the [Network] page.	
					x	-	Improved the visibility of camera setting screen as follows: - Removed unnecessary titles - Switched the position of "Next" and "Back" button	

*: ONVIF is a trademark of Onvif, Inc.

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
						*: ONVIF is a trademark of Onvif, Inc.		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver4.91 (4.50.38) Dec., '21	B			x		Unable to perform multicast transmission. (Occurrence frequency: Rare)	When the camera is started with the following settings: - "DHCP" is selected for "Network Settings" on the[Network] tab of the [Network] page - "Multicast" is selected for [Transmission type]	Fixed.
			x			Recording loss of some frames may occur in SD memory card recording after receiving an alarm. (Occurrence frequency: High)	When post recording is enabled on the camera.	Fixed.
					x	-	-	Improved the accuracy of time synchronization with NTP server.
			x			The camera returns an error and the settings for face matching function cannot be configured on the camera. (Occurrence frequency: High)	Under both of the following conditions: - Enable face matching function on an NX series recorder. - The HTTP port number on the recorder is larger than 256	Fixed.
				x		The camera may get stuck in the log deleting status. (Occurrence frequency: Rare)	When deleting logs on the log list.	Fixed.
				x		Unable to configure OSD settings using the ONVIF command "SetOSD() tt:OSDConfiguration Token"	-	Fixed.
				x		Firmware upgrade may fail. (Occurrence frequency: Rare)	When upgrading the camera(s) connected to WJ-NX100.	Fixed.
					x	-	-	Adjusted the Mic input volume on Google Chrome, Microsoft Edge, and Firefox to be equivalent to Internet Explorer.
					x	Long press on [Manual zoom adjustment] button or [Brightness adjustment] button incorrectly starts text input mode on the button. (Occurrence frequency: High)	On the setup menu of "/tab" window for tablet device.	Fixed.
						x	-	-

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
Ver5.00 (4.60.30) Apr., '22	U				x	-	Changed company name from "Panasonic i-PRO Sensing Solutions Co., Ltd." to "i-PRO Co., Ltd."	
					x	-	Updated SNMP extended MIB: Changed the extended Object ID(OID) from Panasonic(258) to i-PRO(57501). Note: - This change applies only to the products manufactured in April, 2022* or later, and is not applied by firmware upgrade. *Serial number: VDxxxxxx - MIB file and manual are available at the following link: https://i-pro.com/global/en/surveillance/database/i-pro-device-integration/snmp-mib	
Ver5.01 (4.60.30) Aug., '22	U				x	-	Improved to display the image transmission log on the [Status] tab in the [Maintenance] page. Clicking the "Confirm" button of [Image transmission log] displays logs on a separate window.	
					x	-	Supports the notification of i-VMD detection area ID as follows: - Added the [i-VMD alarm area information] on/off setting to the [TCP alarm notification] window on the [Notification] tab. - Improved the response to the CGI command "/cgi-bin/get_io2" by adding the detection area ID.	
					x	-	Removed the [SD memory card images] acquisition function for Internet Explorer (IE) on the [SD memory card] tab, according to the Internet Explorer (IE) end of support.	
					x	-	Enhanced security.	
Ver5.02 (4.60.30) Nov., '22	U				x	-	Changed the company name in the GlobalSign digital certificate installed on the camera to "i-PRO Co., Ltd."	
Ver5.04 (4.60.30) Dec. '22	B		x			The live image may not appear, as the maximum number of users concurrently accessible to the camera decreases. When satisfying all of the following conditions: - Version 5.01 or 5.02 - [Internet mode] is set to Off (Default=On) - H.264/H.265 transmission	Fixed.	

*: ONVIF is a trademark of Onvif, Inc.



This document describes WV-S1432LH/S2532LH/S2132LH/S2132H firmware upgrade Info.
1. Release version: Version 5.08
2. Release Note Reference Number: S1432LH-037

November 28, 2023
i-PRO Co., Ltd.

WV-S1432LH/S2532LH/S2132LH/S2132H Firmware Release Note

WV-S1432LH WV-S2532LH WV-S2132LH WV-S2132H	Priority Rank Level					Contents		
	Priority Rank Level							
	A B C U					Issue (Phenomenon) Occurrence condition Correspondence		
Ver5.05 (4.60.30) Jan. '23	C				x	-	-	Changed company name in the plug-in (ActiveX) software to "i-PRO Co., Ltd."
				x		HTTPS connection is not available until the [Connection] setting is once switched from "HTTP" to "HTTPS", on the HTTPS setting page in the [Advanced] window.	-	Fixed.
Ver5.08 (4.60.30) Nov. '23	U				x	-	-	Improved the productivity at production line.

Important notes:
1. The face detection function does not work when the frame rate is set to 25fps or 50fps.
2. Stabilizer does not work when the frame rate is set to 60 fps, 50 fps, or 25 fps.