

## CJ-HDR108 Firmware Release Note

This document describes CJ-HDR108 firmware upgrade information.

1. Release version: System version 3.200.PS00.1.R, Build date 2020-02-27
2. Release Note Reference Number: CJ-HDR108-003

Mar 10, '20  
Panasonic System Solutions Asia Pacific

| System Version<br>Build date | Priority Rank Level |   |   |   |   | Contents  |                     |  |
|------------------------------|---------------------|---|---|---|---|---|---------------------|--|
|                              | A                   | B | C | U |   | Issue (Phenomenon)  | Occurance condition | Correspondence   |
| 3.200.PS00.0<br>11/11/2015   |                     |   |   |   |   | 1st production.   |                     |  |
| 3.200.PS00.0<br>02/11/2016   | U                   |   |   |   | X | -   | -                   | Added pop up message display that "For the channel 1 and channel 5, the change of the frame rate to 16fps or more at 1080p resolution mode will affect the frame rate settings of other channels "when access to the ENCODE Interface. |
|                              |                     |   |   |   | X | -   | -                   | Changed pop up message "Encode resolution has changed" to "Encode resolution and its frame rate settings have changed. Please check the settings at "Encode" tab."   |
| 3.200.PS00.0<br>10/03/2017   |                     |   |   |   | X | -   | -                   | Improved security  |
| 3.200.PS00.1<br>27/02/2020   |                     | X |   |   |   | When HDD is full, firmware randomly overwrites the HDD storage. | -                   | -  |